

FIG. 1




FIG. 2




FIG. 3





FIG. 4


FIG. 5

FIG. 6

FINISHING DETAILS

☐ WIDEN VALID PRINT AREA
AND PRINT

OK CANCEL RETURN TO
STANDARD HELP

FIG. 7

PROCESSES OF PRINTER DRIVER




FIG. 8

PROCESSES OF PRINTER CONTROLLER




FIG. 9




FIG. 10




FIG. 11

FINISHING DETAILS

☐ WIDEN VALID PRINT AREA AND PRINT

☐ MATCH CENTER OF IMAGE WITH THAT OF SHEET

OK CANCEL RETURN TO STANDARD HELP

FIG. 12

PROCESSES OF PRINTER CONTROLLER





FIG. 13


FIG. 14

FIG. 15




FIG. 16

COMMAND	FUNCTION
MOVE x, y	SET DRAWING START POINT TO (x, y)
LINE TO dx, dy	DRAW STRAIGHT LINE FROM PRESENT COORDINATES TO (+dx, +dy)
SET MODE	SET TO MODE SHOWN BY "MODE"